

Determination D0109EN	Edition: 9 Valid from: 2026-01-26 Review: 2029-01-23	Owner: PEQAC	Everllence
Approval List LO for Distillate Fuel Operation SAE 40			

Applicable for Everllence four stroke medium-speed large bore engines (type 32/40, 32/44, 35/44, 48/60, 49/60, 51/60) and for all engines of the Pielstick brand except PA4 200 ID engines

Company	Oil Brand	BASE NUMBER (mg KOH/g)
Castrol	MLC 40 MHP 154 MHP 1-40	12 15 12
Chevron	HDAX 9700 SAE 40**	5.8
Chevron (Texaco, Caltex)	Delo 1000 Marine 40 Delo SHP40 Taro 12 XP 40 / Taro 12 XP 40 (2) Taro 16 XP 40 / Taro 16 XP 40 (2) Delo 400 TBN10*	12 12 12 16 10
ExxonMobil	Mobilgard 412 (Gp1) / Mobilgard 412 (Gp2) Mobilgard 1SHC Mobilgard ADL 40 (Gp1) / Mobilgard ADL 40 (Gp2) Mobil Delvac 1640 (Gp1) / Mobil Delvac 1640 (Gp2)	15 15.6 12 12
Fuchs Petrolube	Fuchs Titan MarWay 1040*	10.6
Gulf Oil Marine	GulfSea Power MDO 4012S GulfSea Power MDO 4015S	12 15

We do not assume any responsibility for difficulties that might be caused by these oils.

For Pielstick engines, not all recommended lube oils are listed in this document. For more information, please contact your Pielstick technical correspondent.

* Sulfur content in fuel max. 1% (10 000 ppm)

** Sulfur content in fuel max. 0.1% (1 000 ppm)

Determination D0109EN	Edition: 9 Valid from: 2026-01-26 Review: 2029-01-23	Owner: PEQAC	Everllence
Approval List LO for Distillate Fuel Operation SAE 40			

Applicable for Everllence four stroke medium-speed large bore engines (type 32/40, 32/44, 35/44, 48/60, 49/60, 51/60) and for all engines of the Pielstick brand except PA4 200 ID engines

Company	Brand	BASE NUMBER (mg KOH/g)
Shell	Gadinia AL 40 Gadinia S3 Gadinia S4 Sirius X40	15 12 15 17
Sinopec	Marine TPEO 4012 Marine TPEO 4015	13.3 15
SK Lubricants	Supermar 13TP40 Supermar 15TP40	13 15
TotalEnergies	Disola M 4015 Disola M 4012 Disola 4015 Disola 4012 Caprano M 40 Caprano 4015 Caprano 4012	15 12 15 12 14 15 12
Vibra Energia	Marbrax CCD-410 Marbrax CCD-415 Lubrax Marine TP 1-40	12 15 12

We do not assume any responsibility for difficulties that might be caused by these oils.

For Pielstick engines, not all recommended lube oils are listed in this document. For more information, please contact your Pielstick technical correspondent.